

[LOGO]

CLOSET ASSESSMENT

Day 01 Month 07 Year 22

How did you find us: Google Search Site: Google

Customer: Bob Smith

Address: 123 Manyfield Ln, Richmond, VA 15072 Buzzer: —

Phone: 555-123-7676

Email: bob.smith@hotmail.com

Spaces Assessed All: 1 Master

[Have a Niche]

Let the client know complimentary tear out and patching of all holes (not paint) is included. If the patch work is not dried than the client has to sand and paint upon install completion. It is easier to paint the space once closet is installed because the material will cover most of the wall. We will also discard all material, ALL complimentary!

Questions:

1. What is the client timeline? would prefer design completed in 1 week. Install 3 months
2. What is the client budget? (our average job between \$2500-\$3000+) \$10,000
3. How many other quotes have they requested? 1 (one) closet guys
4. Notes:

Customer Name: Bob Smith

OBSTRUCTIONS & MEASUREMENTS:

CURRENT SPACE: Master WALL TYPE: Drywall FLOOR TYPE: Tile
wood studs

Tear Out: (S) (M) (L) Please circle - Comments: _____

Door Opening: W 30 H 80 Type: Swing Door Opening: In or (O)ut

Ceiling Height: 98"

Sloped or Stepped Ceiling: High Point: - Low Point: 97 1/2" Depth: -

Door Trim: W 2 1/2" D 3/4" Casing: W _____ D _____

Baseboard Trim: H 4" D 3/4"

Angles: Wall number - Radius - Length -

Window (outside of Trim) : W 24" H 48" Trim Thickness 2 1/2"

Leveled walls and corners Y N _____ (Visual check) Electrical Panels/Wiring: Y _____ N _____ (Visual check)

Crawl Space or Attic Entrance: Y _____ N H _____

Lighting: Where? Be mindful of its height and how far from L or R wall _____

